

OXFORD DIOCESAN ADVISORY COMMITTEE FOR THE CARE OF CHURCHES

MINUTES OF THE MEETING HELD ON MONDAY 10<sup>TH</sup> MAY 2021

1. **Apologies:** Archdeacon of Dorchester, Revd Canon Dr Peter Groves, David Mason, Maranda St John Nicolle
2. Minutes of the meeting held on 11<sup>th</sup> January 2021
3. Declarations of interest
4. Correspondence, policy and other matters for consideration

Applications submitted to DAC since last DAC agenda:

February 2021 – total 136

List B	Faculty DA	Faculty Minor	Faculty Major	Interim/variation/PP	Early stage Enq
48	8	20	7	8	45

March 2021 – total 131

List B	Faculty DA	Faculty Minor	Faculty Major	Interim/variation/PP	Early stage Enq
40	15	9	15	1	51

5. Returning Casework

Parish & Dedication	App no/ offline:	Archdeaconry	Listing	Private Petition?	Case type:	Case officer:
Bloxham, St Mary	<a href="#">2019-033906</a>	Dorchester	I	No	New Facilities	JS
On Heritage at risk register?	No	SoN to PDA?				No
Scheduled Ancient Monument?	No	Memorials/ burials affected? (send guidance to parish and add public notice wording to OFS)				Yes- setting of memorial ledgers internally affected by west end facilities;
Major Parish Church?	Yes	Trees/roots affected?				No
Bats affected?	No	Energy Audit suggested?				Yes – completed 2019

Proposal:			
Proposed design of curved screens and kitchen, servery, WC and storage facilities at west end of nave and aisles.			
Significance of fabric affected:	Date Submitted to DAC:	Visited:	Report:
Medieval and Street interior- high	May 2019, November 2019, and November 2020	April 2019	NOA issued April 2021
Statutory Consultees:		Project architect/ professionals involved:	Reviewing DAC members:
Historic England	YES	Jeremy Bell - JBKS	David Clark, Rev Jeff West, Joyce Christie, Julian Munby, Archdeacon of Dorchester, Abigail Lloyd
CBC	YES		
SPAB	YES		
Victorian Society	YES		
Georgian Group	NO		
AMS	NO		
20 <sup>th</sup> Century Society	NO		
LPA (PP)	NO		
LPA (Sch 2)	YES		
BIOS	NO		
MBS	NO		
Natural England	NO		
Is Rule 9.6 applicable?		YES	
Is Rule 9.9 applicable?		YES	
<b>May 2021 minute:</b>			
<p>A <i>Not Object</i> NOA for the provision of facilities within two curved pods at the west end of the nave was issued on 19 April 2021 to allow the Chancellor to consider the application in the light of objections raised by Historic England, the Church Buildings Council and the amenity societies. Revised proposals for the design of the enclosing screens and layout of the facilities were discussed by the committee. Members expressed concerns about the proposed design which they felt would not complement the interior of the Grade I listed church which is considered one of the grandest in the country. Concerns were also expressed about the extent of the kitchen facilities for which insufficient justification has been provided. Further revision of the proposals to be requested by proviso once the application has been determined by the Chancellor.</p>			

Parish & Dedication	App no/ offline:	Archdeaconry	Listing	Private Petition?	Case type:	Case officer:
Eynsham St Leonard	<a href="#">2020-049548</a>	Dorchester	II*	NO	Extension	LK
On Heritage at risk register?	No	SoN to PDA?				No
Scheduled Ancient Monument?	No	Memorials/ burials affected? (send guidance to parish and add public notice wording to OFS)				Yes – spoil in churchyard
Major Parish Church?	No	Trees/roots affected?				Yes
Bats affected?	No	Energy Audit suggested?				Yes
Proposal:						
Construction of a new church centre in the recently purchased car park adjoining the church site. To connect to the church via the mid 20th Century organ chamber. Associated alterations to the church interior and churchyard. Reorientation of church interior and enclosure of chancel to provide a creche. New heating.						
Significance of fabric affected:	Date Submitted to DAC:		Visited:		Report:	
Moderate	Nov 19, Apr 2021		9.12.19		13.3.20	
Statutory Consultees:		Project architect/ professionals involved:			Reviewing DAC members:	
Historic England	YES	MEB			Jeff West, Julian Munby, Helen Ensor, Bryan Martin, David Tyler	
CBC	YES					
SPAB	YES					
Victorian Society	NO					
Georgian Group	NO					
AMS	NO					
20 <sup>th</sup> Century Society	YES					
LPA (PP)	YES					
LPA (Rule 4.5)	YES					
BIOS	NO					
MBS	NO					
Natural England	NO					
Is Rule 9.6 applicable? NO						
Is Rule 9.9 applicable? YES						
Statutory Consultees	Comments					
ROUND ONE – NOV 19						
LPA	The principle of developing the site is acceptable, however the scale and volume of the proposals need to be reduced and the design needs to stand alone and not be linked to the church. The proposed changes to the boundary wall and pathways surrounding the war memorial are likely to be acceptable subject to revised parking provisions.					

ROUND TWO – DEC 19	
LPA	No response received.
HE	Produce a project brief with all user groups and needs identified. Consider church interior space too. Content with principle of a new building, the glazed link and link location, will need to see design as it progresses.
CBC	Building the basement structure and lift would involve costly excavation and archaeological investigation. Concern that the amount of cost involved may exceed the value of the space gained, especially if most of the basement level is to be used for storage purposes. Suggested reassessing the need for the basement component of the scheme. The statement of significance could say more about the importance of known archaeology of the Saxon Burgh of which the church and former abbey were important components. proposed layout may not be the most efficient use of space. asked that the parish think carefully about whether such a large hall space is required given that the village already has several halls (eleven halls were mentioned on site). Suggested that any large-scale activities outside of Sunday services could be held in the un-pewed nave. It appears that the primary purpose of the proposed extension is to have a safe and accessible space where church activities can take place. As such, the Council queried whether the hall component of the proposal was required and if a series of offices and meeting rooms would be sufficient for its needs.
SPAB	Encouraging use of church interior. Accepts need. Content with principle of link – but success down to details. Consider use of the organ chamber space. Comment on form and mass of hall. Suggests avoiding a basement.
DAC Advice:	
<p><b>May 2021 Minute:</b></p> <p>The DAC felt that the design as proposed was not sensitive to its surroundings, including the church, neighbouring Scheduled Ancient Monument, the listed Red Lion pub, and the square itself. The DAC’s comments on the design, although informed entirely by their own review of the scheme (in fact the DAC committee had not seen the 6<sup>th</sup> May Pre app letter as I did not have time to forward it to them before the meeting) echoed many of those within the latest LPA Pre-application Advice letter. The committee felt that the nature of the revised proposals did not constitute minor revisions but are actually a considerable departure from what had been proposed in previous rounds of consultation, and which had gained some degree of support in principle, subject to details being worked out. Major changes have been made to the scope and scale of the proposals, both in the design of the centre and also the alterations proposed to the church. The proposed elevational treatment and scale of the new centre are radically different to what was previously proposed. The previous pitched roof design echoed that of the chancel with possible glazed gable to preserve some sight lines. In contrast, the newly proposed modern monopitch lines cut across the lines of the church and would have a far more considerable impact on the setting of the church itself than the previous design iteration. The view of the new church centre through the east window of the church should also be considered.</p> <p>The new proposals bring the corridor linking the centre and the church northwards of the organ chamber itself, creating a more significant visual impact on the church building than the glazed link from the east of the organ chamber would have, as seen in earlier proposals. The precedent image of the new glazed porch to Sutton Valence school does not communicate a lightweight, subservient structure. The scale and number of the structural elements are far more dominant in that example than would be acceptable for use on a grade II* listed church. The function of a new glazed porch is also unclear. In addition, it is not clear why a new main entrance to the church is proposed at all. The circulation of people within the church building remains of concern, as does the location and number of toilets retained in the building, and the lack of justification for re-orientating the worship space or enclosure of the chancel. Options for providing an enclosed space (if necessary) and serving and toilet facilities within the church building should be explored,</p>	

to assess whether this can be achieved more successfully and with less harm caused to the significant church interior.

Fundamentally it appears that a separate room is provided for each of the functions carried out by the church team, and that causes the scale of the proposed centre, and the interventions within the church, to increase. The DAC would like to understand whether this is the case, and understand exactly what activities are to take place in each proposed space.

The DAC expressed concern that the appointed architects had not been provided with the actual consultation responses themselves, and that perhaps they had not seen the earlier design sketches submitted to the LPA for pre app advice. Had that, and discussion with the DAC team soon after the architect's appointment, happened, feedback such as this, which I am sure the parish will find deeply frustrating to receive, may have been avoided.

Due to the number and severity of the concerns raised, the DAC resolved not to comment on any elements of the scheme in detail prior to visiting again to discuss the revised proposals on site with the design and project teams. The committee understands that the interior alterations to the church itself are proposed to be a later phase, but the design for the whole site must be considered holistically. The proposals for the centre, link and hall are intrinsically linked and the design approach should reflect that, even if the project is executed in phases.

## 6. Pre – application or technical site visits by officers to note (19.02.20 – 28.04.21)

- 13.04.21 Marcham All Saints – removal of pews (JS)
- 14.04.21 Edgcott St Michael & All Angels – possible closure (LK)
- 15.04.21 Chilton St Mary – reordering (LK)
- 15.04.21 Oxford St Mary the Virgin – roof repair (JS)
- 20.04.21 Northmoor St Denys – floor repairs (JS)
- 23.04.21 Hampton Poyle St Mary the Virgin – new facilities (JS)
- 28.04.21 Fawley St Mary – reordering (AF and LK)

## 7. New cases

Parish & Dedication	App no/ offline:	Archdeaconry	Listing	Private Petition?	Case type:	Case officer:
Wraysbury St Andrew	2020-052108	Buckingham	II*	NO	Disposal of chalice	NM
On Heritage at risk register?	No	SoN to PDA?				No
Scheduled Ancient Monument?	No	Memorials/ burials affected? (send guidance to parish and add public notice wording to OFS)				No
Major Parish Church?	No	Trees/roots affected?				No

Bats affected?	No	Energy Audit suggested?	No
Proposal:			
Disposal of chalice			
Significance of fabric affected:	Date Submitted to DAC:	Visited:	Report:
Low	May 2020	NA	NA
Statutory Consultees:		Project architect/ professionals involved:	Reviewing DAC members:
Historic England	NO	Bonhams	Derek Witchell
CBC	NO		
SPAB	NO		
Victorian Society	NO		
Georgian Group	NO		
AMS	NO		
20 <sup>th</sup> Century Society	NO		
LPA (PP)	NO		
LPA (Sch 2)	NO		
BIOS	NO		
MBS	NO		
Natural England	NO		
Is Rule 9.6 applicable? NO			
Is Rule 9.9 applicable? NO			
<p><b>May 2021 Minute:</b></p> <p>Having reviewed the information supplied the DAC deferred a decision on the disposal, which they considered was precipitous at this point as the justification was felt insufficient and not enough is known about the chalice to reach an informed decision. The DAC felt that further investigation into the provenance and significance of the chalice was needed prior to DAC support being given to a faculty application for its disposal. The DAC were also unclear how the imagery was considered not appropriate for use in a Christian setting.</p> <p>It was suggested that the item may have cultural value in Burma and that it may be appropriate to contact the Burmese Embassy and national museum for help establishing this. DAC member, John Missenden, may be able to assist in this endeavour.</p>			

Parish & Dedication	App no/ offline:	Archdeaconry	Listing	Private Petition?	Case type:	Case officer:
Witney St Mary	<a href="#">2021-061096</a>	Dorchester	II	NO	Introduction of icons	LK
On Heritage at risk register?	No	SoN to PDA?				No
Scheduled Ancient Monument?	No	Memorials/ burials affected? (send guidance to parish and add public notice wording to OFS)				No
Major Parish Church?	No	Trees/roots affected?				No
Bats affected?	No	Energy Audit suggested?				No
Proposal:						
Introduction of icons of St Luke and St Frideswide to be located in the St George Chapel.						
Significance of fabric affected:	Date Submitted to DAC:	Visited:		Report:		
High	April 2021	NA		NA		
Statutory Consultees:		Project architect/ professionals involved:			Reviewing DAC members:	
Historic England	NO	Dr Irina Bradley			Peter Groves	
CBC	YES					
SPAB	NO					
Victorian Society	NO					
Georgian Group	NO					
AMS	NO					
20 <sup>th</sup> Century Society	NO					
LPA (PP)	NO					
LPA (Sch 2)	NO					
BIOS	NO					
MBS	NO					
Natural England	NO					
Is Rule 9.6 applicable? YES						
Is Rule 9.9 applicable? NO						
<b>May 2021 Minute:</b>						
The DAC were supportive of the proposal in principle but would like some further information prior to issue a supportive Notification of Advice for the application.						
The DAC noted that the proposed area looks to be a medieval aumbry with a later St George statue, and as such may be an appropriate place for the new icons to be installed. However, no information on the history or significance of this area of the church, or why it had been selected as the appropriate location had been						

provided. Additionally, the DAC would be interested to hear the connection of St Luke and St Frideswide with the church, and why these two saints had been chosen to sit within a church dedicated to St Mary, in a chapel dedicated to St George. Some interpretation for visitors may also be helpful to explain this. The DAC are also aware that other future proposals are being considered at St Mary's and were keen to hear of how the introduction of the icons fits within the wider project plans.

The DAC delegated the matter to Jeff West and David Tyler to consider once the additional information is available.

Parish & Dedication	App no/ offline:	Archdeaconry	Listing	Private Petition?	Case type:	Case officer:
Cottisford St Mary	<a href="#">2020-057148</a>	Dorchester	II*	NO	New facilities	HR
On Heritage at risk register?	No	SoN to PDA?				No
Scheduled Ancient Monument?	No	Memorials/ burials affected? (send guidance to parish and add public notice wording to OFS)				No
Major Parish Church?	No	Trees/roots affected?				No
Bats affected?	No	Energy Audit suggested?				No
Proposal:						
West end reordering and creation of an extension to provide accessible WC, servery, vestry area and gathering space.						
Significance of fabric affected:	Date Submitted to DAC:		Visited:		Report:	
High - C13 <sup>th</sup>	14.12.2020		09.12.19 & 28.04.21		Pre-app 09.12.2019	
Statutory Consultees:		Project architect/ professionals involved:			Reviewing DAC members:	
Historic England	YES	Bryan Martin			Peter Preston, Abigail Lloyd, Helen Ensor, Julian Munby & David Tyler	
CBC	NO					
SPAB	YES					
Victorian Society	NO					
Georgian Group	NO					
AMS	YES					
20 <sup>th</sup> Century Society	NO					
LPA (PP)	YES					
LPA (Rule 4.5)	YES					
BIOS	NO					
MBS	NO					



Natural England	NO	
Is Rule 9.6 applicable?	NO	
Is Rule 9.9 applicable?	YES	
<p><b>May 2021 minute:</b>  The DAC resolved to provide in principle support for the proposals based on option 8 with resolution of details delegated to a subcommittee. The character of the church largely stems from its 13<sup>th</sup> origins, tall and narrow with small high windows. The interior is small, yet light and welcoming. The preferred scheme will result in a simple layout and will improve the cluttered and impractical west end.</p> <p>Externally, the scheme does not have an impact on the character of the church when viewed from the south, the principle elevation. The proposed extension is of a modest size and draws on the main building in its design and materials.</p>		

8. List Bs and Notifications of Advice issued under sub committees and delegated authority since last meeting

Code	Parish	CofE Archdeaconry	Listing	Application Ref	App Type	Case type	Works	Status
627581	Denham: St Mary the Virgin	BUCKINGHAM	Grade I	offline	Enquiry - email	Churchyard	Variation to Churchyard regs - kerbs around graves	Awaiting Diocesan Registry
627581	Denham: St Mary the Virgin	BUCKINGHAM	Grade I	offline	Enquiry - email	Churchyard	Variation to Churchyard regs - kerbs around graves	Awaiting Diocesan Registry
627507	Faringdon: All Saints	DORCHESTER	Grade I	2019-031340	Faculty - DA	Churchyard	Installation of CCTV cameras	NOA issued with provisos
627425	Leckhampstead: St James - HAR	BERKSHIRE	Grade II*	2021-059589	Faculty - DA	Disposal of items	Removal of old Altar, curtain rail and pulley chain	Petition submitted to Dio Reg
627741	Mursley: St Mary the Virgin	BUCKINGHAM	Grade II*	2021-058269	Faculty - DA	M&E	AV works	Registrar to issue faculty
627477	Woodley: St John the Evangelist	BERKSHIRE	Grade II*	2021-057836	Faculty - DA	M&E	New AV System	NOA issued with provisos
827007	St Peters College Chapel Oxford	OXFORD	Grade II	2020-057072	Faculty - DA	Seating	Restoration of 3 wainscot chairs	Petition submitted to Dio Reg
627170	Henley-on-Thames: St Mary the Virgin MAJOR PARISH CHURCH	DORCHESTER	Grade II*	2021-058932	Faculty - DA	Churchyard	Churchyard boundary repairs	Petition submitted to Dio Reg
627417	Hungerford: St Lawrence	BERKSHIRE	Grade II*	2020-056762	Faculty - DA	M&E	New AV System	Registrar to issue faculty
627429	Shaw-cum-Donnington: St Mary	BERKSHIRE	Grade II	2020-054571	Faculty - DA	R&C	Replacement of damaged south doors	Registrar to issue faculty
627360	Theale: Holy Trinity	BERKSHIRE	Grade I	2021-060040	Faculty - DA	M&E	Introduction of fixed foldable screen and projector in the chancel	Awaiting DAC Officer
627057	Piddington: St Nicholas	DORCHESTER	Grade II*	2020-049507	Faculty - Major	New facilities	Installation of wc, servery, memorial plaque & positioning of defibrillator	Petition submitted to Dio Reg

627084	Leafield: St Michael & All Angels	DORCHESTER	Grade II*	2020-054167	Faculty - Minor	Churchyard	Retrospective: New path through churchyard to burial ground extension	Registrar to issue faculty
627769	Olney: St Peter & St Paul	BUCKINGHAM	Grade I	2020-054046	Faculty - Minor	Development	Creation of a John Newton (Olney curate) heritage corner in the south aisle.	petition submitted to Dio Reg
627426	Newbury: St John the Evangelist	BERKSHIRE	Grade II	2019-035568	Faculty - Minor	Development	Installation of ramp and glazed outer porch	NOA issued with provisos
627699	Preston Bissett: St John the Baptist	BUCKINGHAM	Grade II*	2021-057943	Faculty - Minor	M&E	Installation of telecommunications equipment on church tower	Petition submitted to Dio Reg
627134	Barford: St Michael (Parish considering closure)	DORCHESTER	Grade I	2020-056805	Faculty - Minor	Seating	Regularise TRO - remove 2 pews and re-arrange 4	Petition submitted to Dio Reg
627285	Sandford: St Martin	DORCHESTER	Grade II*	2020-052746	Faculty - Minor	R&C	Repairs to Tower, Aisles & Porch, rainwater & drainage; Internal safety improvements	Registrar to issue faculty
627458	Reading: St John the Evangelist & St Stephen	BERKSHIRE	Ungraded	2020-056661	Faculty - Minor	R&C	Windows, insulation & cavity wall works	NOA issued
627344	Bradfield: St Andrew CLOSED CHURCH	BERKSHIRE	Grade II*	2020-048605	Faculty - Minor	Churchyard	Creation of area for the interment of ashes within churchyard	Petition submitted to Dio Reg
627136	Bloxham: Our Lady of Bloxham MAJOR PARISH CHURCH	DORCHESTER	Grade I	2021-059527	Faculty - Minor	R&C	Repairs to Street tile floor scheme	NOA issued with provisos
627136	Bloxham: Our Lady of Bloxham MAJOR PARISH CHURCH	DORCHESTER	Grade I	2021-059503	Faculty - Minor	M&E	Replacement and upgrading of heating installation	Petition submitted to Dio Reg
627136	Bloxham: Our Lady of Bloxham MAJOR PARISH CHURCH	DORCHESTER	Grade I	2019-033906	Faculty - Major	New Facilities	Installation of new facilities in curved pods	NOA issued with provisos
627701	Steeple Claydon: St Michael	BUCKINGHAM	Grade II*	2021-058716	Faculty - Minor	M&E	Proposed AV installation	Petition submitted to Dio Reg
627779	Drayton Beauchamp: St Mary the Virgin	BUCKINGHAM	Grade I	offline	Interim	R&C	Surface water drainage works - investigative works	Interim faculty issued
627740	Mentmore: St Mary the Virgin	BUCKINGHAM	Grade II*	offline	Interim	New facilities	Installing wifi through Village Networks	Interim faculty issued
627271	North Aston: St Mary the Virgin	DORCHESTER	Grade II*	offline	Interim	Liturgical	The use of a table as an altar	Interim faculty issued
627475	Reading: St Agnes w St Paul	BERKSHIRE	Ungraded	2021-060848	List B	M&E	New Boilers	Awaiting Archdeacon
627100	Beckley: Assumption of the Blessed Virgin Mary	DORCHESTER	Grade I	2020-056957	List B	R&C	reroofing of the chancel & masonry repairs	List B issued
627006	Brightwell Baldwin: St Bartholomew	DORCHESTER	Grade I	2020-056168	List B	R&C	Emergency repairs re plaster fall	List B issued
627499	Bourton: St James	DORCHESTER	Ungraded	2020-046652	List B	R&C	Repair of retaining wall to redundant	List B issued

							below ground boiler room	
627224	Oxford: St Matthew	OXFORD	Ungraded	2021-060067	List B	R&C	Painting north & south walls	List B issued
627505	Little Coxwell: St Mary	DORCHESTER	Grade II*	2021-060538	List B	M&E	New sound system	List B issued
627591	Holmer Green: Christ Church	BUCKINGHAM	Ungraded	2021-058893	List B	Churchyard	Felling dead tree	List B issued
627708	Wotton Underwood: All Saints	BUCKINGHAM	Grade II*	2021-058449	List B	R&C	Replacement of copper on Steeple	List B issued
627449	Earley: St Nicolas	BERKSHIRE	Ungraded	2021-059161	List B	Churchyard	Removal of yew tree from Montessori Garden	List B issued
627827	High Wycombe: All Saints MAJOR PARISH CHURCH	BUCKINGHAM	Grade I	2021-058685	List B	Heritage Crime	Repair Windows following vandalism	List B issued
627709	Bletchley: St Mary	BUCKINGHAM	Grade I	2021-059632	List B	Churchyard	War Graves plaque on entrance wall	List B issued
627808	Hughenden: St Michael - HAR	BUCKINGHAM	Grade II*	2021-058942	List B	M&E	Video streaming equipment	List B issued
627514	Charney Bassett: St Peter	DORCHESTER	Grade I	2021-059810	List B	M&E	introduction of internet connection and AV	List B issued
627585	Fulmer: St James	BUCKINGHAM	Grade II*	2021-058938	List B	Churchyard	Memorial bench in churchyard (Dorling)	List B issued
627234	Bampton Aston: St James	DORCHESTER	Grade II	2021-059464	List B	Churchyard	Replacement noticeboard	List B issued
627338	Winkfield: St Mary the Virgin	BERKSHIRE	Grade II*	2021-059311	List B	M&E	Enq re speakers and wall	List B issued
627473	Tilehurst: St Michael	BERKSHIRE	Grade II	2021-059260	List B	Churchyard	New bench in Churchyard	List B issued
627295	Abingdon: St Helen MAJOR PARISH CHURCH	DORCHESTER	Grade I	2021-060387	List B	M&E	Installation of external light	List B issued
627475	Reading: St Agnes w St Paul	BERKSHIRE	Ungraded	2021-060856	List B	R&C	Replacement of carpet in Chancel	List B issued
627475	Reading: St Agnes w St Paul	BERKSHIRE	Ungraded	2021-060854	List B	H&S improvements	New Intruder Alarm	List B issued
627475	Reading: St Agnes w St Paul	BERKSHIRE	Ungraded	2021-060852	List B	R&C	Redecoration and making good water damage	List B issued
627475	Reading: St Agnes w St Paul	BERKSHIRE	Ungraded	2021-060849	List B	M&E	Urgent electrical installation equipment	Awaiting Archdeacon
627562	Amersham: St Mary the Virgin	BUCKINGHAM	Grade I	2021-060489	List B	M&E	Video streaming for services, fixed AV equipment and CCTV	List B issued
627644	Stowe: Assumption of the Blessed Virgin Mary	BUCKINGHAM	Grade II*	2021-060475	List B	Churchyard	Introduction of a bench in the churchyard	List B issued
627752	Wingrave w Rowsham: St Peter & St Paul	BUCKINGHAM	Grade II*	2021-060949	List B	Churchyard	Wooden bench in churchyard adjacent to existing bench	Awaiting Archdeacon
627094	Swerford: St Mary	DORCHESTER	Grade II*	2021-059183	List B	H&S improvements	Introduction of Handrail	List B issued
627128	Adderbury: St Mary HAR	DORCHESTER	Grade I	2021-058534	List B	Churchyard	Dry stone wall repairs in Churchyard	List B issued

627158	Swalcliffe: St Peter & St Paul	DORCHESTER	Grade I	2021-060265	List B	Churchyard	Repair of collapsed section of boundary wall	List B issued
627179	Rotherfield Greys: St Nicholas	DORCHESTER	Grade II*	2021-060219	List B	R&C	Replacement door lock	List B issued
627259	South Leigh: St James the Great	DORCHESTER	Grade I	2021-058476	List B	R&C	Replace ringing room carpet	List B issued
627274	Cassington: St Peter	DORCHESTER	Grade I	2021-059114	List B	R&C	Replacement of stone to south wall of nave	List B issued
627308	Kennington: St Swithun	DORCHESTER	Ungraded	2021-059005	List B	Churchyard	Anchor two new benches in church grounds	List B issued
627311	Garford: St Luke	DORCHESTER	Grade II	2021-059170	List B	Churchyard	Introduction of bench in churchyard	List B issued
627363	Basildon: St Stephen	BERKSHIRE	Ungraded	2021-058648	List B	Churchyard	Felling a dangerous tree	List B issued
627397	Brightwalton: All Saints	BERKSHIRE	Grade II*	2020-056556	List B	Churchyard	Replacement bench with memorial inscription	List B issued
627604	Dinton: St Peter & St Paul	BUCKINGHAM	Grade I	2021-058726	List B	R&C	Repairs to porch roof	List B issued
627609	Haddenham: St Mary the Virgin	BUCKINGHAM	Grade I	2021-058917	List B	R&C	External masonry repairs, gutter redecoration and clock face repairs	List B issued
627701	Steeple Claydon: St Michael	BUCKINGHAM	Grade II*	2020-055411	List B	Churchyard	Graveyard bench	List B issued
627701	Steeple Claydon: St Michael	BUCKINGHAM	Grade II*	2021-059259	List B	Churchyard	Treeworks - WPD	List B issued
627725	Wolverton: Holy Trinity	BUCKINGHAM	Grade II*	2021-058953	List B	Churchyard	New wooden bench in churchyard	List B issued
627787	Little Missenden: St John the Baptist	BUCKINGHAM	Grade I	2021-058709	List B	R&C	Minor repairs to tower & porch	List B issued
627806	Widmer End: The Good Shepherd	BUCKINGHAM	Ungraded	2021-060156	List B	Disposal of items	Disposal of disused items	List B issued
627052	Middleton Stony: All Saints	DORCHESTER	Grade II*	2021-057900	List B	R&C	QI Repairs	List B issued
627130	Banbury: St Mary HAR MAJOR PARISH CHURCH	DORCHESTER	Grade I	2021-058182	List B	H&S improvements	Fire alarm system upgrade	List B issued
627234	Bampton Aston: St James	DORCHESTER	Grade II	2021-058101	List B	Churchyard	Introduction of bench in the churchyard	List B issued
627295	Abingdon: St Helen MAJOR PARISH CHURCH	DORCHESTER	Grade I	2021-057804	List B	M&E	Installation for streaming of services	List B issued
627354	Purley: St Mary the Virgin	BERKSHIRE	Grade II*	2021-059944	List B	M&E	Telephone line & WiFi	List B issued
627421	Inkpen: St Michael	BERKSHIRE	Grade II*	2021-059431	List B	OBC	Cleaning and refurbishment of 1965 Walker pipe organ with donation	List B issued
627493	Wokingham: All Saints	BERKSHIRE	Grade II*	2021-057784	List B	Churchyard	Treework in Churchyard	List B issued
627553	West Hendred: Holy Trinity	DORCHESTER	Grade I	2021-058013	List B	R&C	North aisle roof beam repairs	List B issued
627558	Emberton: All Saints	BUCKINGHAM	Grade II*	2020-057129	List B	Churchyard	Felling of dangerous Lawson cypress	List B issued
627587	Holtspur: St Thomas (Parish considering closure)	BUCKINGHAM	Ungraded	2021-058888	List B	M&E	Upgrade to AV equipment	List B issued

627725	Wolverton: Holy Trinity	BUCKINGHAM	Grade II*	2021-057857	List B	Churchyard	Remove lower branches of Cedar of Lebanon Tree	List B issued
627014	Ewelme: St Mary the Virgin	DORCHESTER	Grade I	2021-058637	List B	R&C	Repair lead downpipe	List B issued
627158	Swalcliffe: St Peter & St Paul	DORCHESTER	Grade I	2021-059254	List B	Churchyard	Felling of one holly tree and crown reduction of second tree which have become dangerous	List B issued
627249	Fulbrook: St James the Great	DORCHESTER	Grade II*	2021-059769	List B	Churchyard	Bench in memory of Joan Marsh	List B issued
627276	Duns Tew: St Mary Magdalen	DORCHESTER	Grade II	2021-059920	List B	Churchyard	Replacement notice board	List B issued
627321	Wootton: St Peter	DORCHESTER	Grade II	2021-060326	List B	R&C	Repair to stained glass window	List B issued
627389	White Waltham: St Mary the Virgin	BERKSHIRE	Grade II*	2021-059405	List B	M&E	Hearing Loop	List B issued
627594	Aylesbury: St Mary the Virgin MAJOR PARISH CHURCH	BUCKINGHAM	Grade I	2021-059997	List B	M&E	External lighting units	List B issued
627598	Bledlow: Holy Trinity	BUCKINGHAM	Grade I	2021-060256	List B	Churchyard	Tree works by parish council	List B issued
627473	Tilehurst: St Michael	BERKSHIRE	Grade II	offline	Private Petition	Churchyard	Memorial outside guidelines (Beeton)	Petition submitted to Dio Reg
627397	Brightwalton: All Saints	BERKSHIRE	Grade II*	2016-006504	Variation	OBC	Introduction of new electronic organ	Amended faculty issued
627093	Spelsbury: All Saints - HAR	DORCHESTER	Grade II*	2020-051309	Variation	R&C	Repair of the chancel, north and south transept, and south aisle roofs with stone slates	Amended faculty issued

## 9. Completed projects feedback

Aylesbury, St Mary and Clifton Hampden, St Michael