

#### 4. THE STEPS ON THE WEST OF THE TOWER



The lower window on the west wall of the tower has been enlarged and converted to a doorway to the bellringers' chamber. The stone steps leading to the door and the iron handrail were installed soon after November 1845, when Sir Samuel Meyrick wrote to a friend about it. Access to the floors inside is by ladder. A steep ascent leads to the bell chamber itself from the ringers' chamber. A full description of the bells can be found in the Heritage Trail for inside the church.

The handrail and steps have been repaired as part of the 2017 Heritage Lottery- funded project.