

Photographs taken on 1st July 2019, near the end of the tower work.

Superb brick-pointing work, freehand moulding, clock-face revamp and of course the complete restoration of the SW pinnacle and weathervane and famous cockerel atop. The louvres' replacement will follow.





Treated louvres on N face – good condition



Poor condition of louvres on S face
-will be replaced from inside the tower



